

Case No.	Respondent	Summary of Findings	Summary of Board Action
NOVEMBER 27, 2007			
M05-227 M06-271	Philip Wayne Rosendahl P.E. (Civil) #24718 Land Surveyor #24532	<p>On or about January 1997 to October 1998, Respondent allowed his seal and signature to be applied to approximately seven (7) building pad compaction reports and failed to review the building pad compaction reports before they were provided to the client.</p> <p>On or about January 1997 through May 1998, Respondent prepared Geotechnical Subsoil Investigation Reports for various commercial projects that are deficient. Respondent failed to perform field tests to identify engineering properties of the insitu soils; failed to perform adequate laboratory testing to determine engineering properties of the soils; failed to provide anticipated building loads and failed to provide recommendations for repairing site soils disturbed by the excavation of exploratory test pits.</p> <p>On or about October 29, 1998, Respondent prepared a Geotechnical Subsoil Investigation Report for a residential project that is deficient. Respondent failed to perform adequate laboratory testing to determine the engineering recommendations in his report with respect to foundation support, engineering properties of the soil, and the effects of wetting on foundation soils and slab-on-grade support, including site preparation and grading procedures. Respondent failed to perform field tests to identify engineering properties of the insitu soils.</p> <p>On or about October 17, 2005, Respondent prepared and sealed a Final Plat that is deficient. Respondent failed to describe existing monuments that he found and used; found and used existing monuments that were not tagged; and failed to place his Registered Land Surveyor number to the untagged monuments.</p>	<p>Letter of Reprimand</p> <p>Administrative Penalty – Pay an administrative penalty of \$5,000.00.</p> <p>Professional Education – Respondent shall take and successfully complete a course in the area of geotechnical engineering.</p> <p>Amend Survey – Respondent shall amend his survey and record it with the Maricopa County Recorder's Office.</p> <p>Cost of Investigation – Pay cost of investigation in the amount of \$1,785.00.</p>
M07-028	AKA Architecture, LLC	On or about July 2005 through October 16, 2006, Respondent Firm provided architectural services in the State of Arizona without registration.	<p>Administrative Penalty – Pay an administrative penalty of \$500.00.</p> <p>Cost of Investigation – Pay cost of investigation in the amount of \$75.00.</p>
M07-093	M.E. Evans & Associates, Inc.	On or about August 2005 through April 19, 2007, Respondent Firm provided engineering services in the State of Arizona without registration.	<p>Administrative Penalty – Pay an administrative penalty of \$800.00.</p> <p>Cost of Investigation – Pay cost of investigation in the amount of \$75.00.</p>

M07-097	Yurkovic Design, Inc.	On or about April 2002 through July 2004, Respondent Firm engaged in the practice of architecture by providing architectural services in the State of Arizona without registration.	<p><i>Assurance of Discontinuance</i> – Respondent Firm shall not practice, offer to practice, or by any implication hold itself out as qualified to practice Architecture as defined by A.R.S. §§ 32-101(B)(2) and (4) in the State of Arizona until Respondent Firm is registered by the Board as required by A.R.S. § 32-141.</p> <p><i>Civil Penalty</i> – Pay a civil penalty of \$2,000.00.</p> <p><i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$200.00.</p>
M07-110	Shreeve GPS Services, LLC	On or about January 2007 through June 2007, Respondent Firm provided land surveying and engineering services in the State of Arizona without registration.	<p><i>Administrative Penalty</i> – Pay an administrative penalty of \$500.00.</p> <p><i>Cost of Investigation</i> – Pay cost of investigation in the amount of \$75.00.</p>